PHANT SERVICES

24 Brushwood Drive Rouse Hill NSW 2155

	PI	ant F	Report	<u>t</u>			: 0428 240 448
Owner: MAEDA Make: -MAEDA	DEKSH	10P			305 S/N	o: <u>D</u>	3099
Inspection: Service: Warranty:		-			r: 161		
Copy Of Certificates Crane Hoist Ropes Main Auxiliary Hooks Main Auxiliary	Attac Yes/N Yes/N Yes/N Yes/N	0 0 0	Y	urren es/No es/No es/No es/No			
Description		OK			Remarks		
Engine			O				4
Oil Leaks Water leaks		1	CHAN	CEY	OIL & FIL	TERS	
Radiator/heater hose condition							
	-t						
Vee belt condition and adjustmer Fan bearing condition	Ц	MA					
Air induction system		ITA					
Air cleaner restrict level		/	Altin E	EMT	NT FITTED		
Exhaust system/muffler			IVEN L	LETTE	IOI FILLED		
Radiator core condition		-					
Engine Mounts		-					
Battery condition/leads		/					
Drain air tanks		NIA	1				
Drive Train							
Transmission oil leaks			1				
Wheel hub/axle oil leaks		N		-	P		
Wheel nuts/locks		A					
Drive shaft/uni joints/drive tracks		/	Hus o	IL C	HANGED		
Tyre condition: % / pressure PS	:		Axle 1	LH		RH	_
			Axle 2	66 33	,	66 37	3
			Axle 3	66 99		""	
		M/A	Axle 4	11 33	-	LL 37	
			Axle 5	66 99		u 33	
			Axle 6	11 33		u 33	
Axle pivot condition							
Axle pivot lock out		/					

Plant Report cont.

S/No: 3099

Date: 10.09.2025

Description	OK	Rema	arks
Steering/Braking System			
Steering cylinder oil leaks			
Tie rod condition			
Tie rod end condition	NA		
Service brake operation/adjustment			
Park brake operation/adjustment			
Fluid level service/park	/		*
Winches		Main	Auxiliary
Mounting bolts	1		
Oil leaks – gear box			/
Oil leaks – hydraulic motor			
Brake linings/adjustment	/	INTERNAL	A) /
Brake oil/fluid leaks			10 A
Drum cracks	/	VISUAL CHECK	
Safety pawl operation	MA		
Disorderly rope winding	5		
Oil level/gear box		OIL CHANGED	/
Ropes and Hooks		·	
Rotation of hook			
Deformation of hook			
Safety latch fitted			
Deformation of rope guard			
Rotation of sheaves			10/
Lubricate sheaves	NA	*	/ 1
Kinks in wire rope	1		
Broken strands in rope	1		
Corrosion of rope	1		
Wedge correctly fitted	1		
Rope clip fitted to end		3	
Slew System			
Slew table cracks	1	VISUAL CHECK	
Slew motor leaks	/		. *
Slew box leaks	/		
Slew box mounting bolts	1		
Slew box oil level	1	DIL CHANGES	
Slew brake operation	1		
Rotary connection leaks	/		9
Upper house lock pin	NA		

Plant Report cont.

S/No: 3099

Date: 10-09-2025

Description	OK	Remarks
Boom		
Hoist cylinder leaks		
Hoist cylinder pins and retainers	/	GREASED
Hoist cylinder hose condition		
Boom pivot pin and retainers	1	(TREASE)
Inspection of boom cracks/damage		VISHAL CHECK
Sliding wear pad condition	1	GREASED
Tele cylinder leaks		
Tele cylinder hoses		
Angle indicator condition		
Inspect fly damage		
Fly retaining pins	MA	. :
Fly storage correct		
Boom sheaves		
Fly sheaves	NA	
Cab And General		
Operation of all gauges		
Control levers/play		
Load meter		
Warning buzzers	1	
Windscreen condition	N	
Wiper condition	A	
Anti two block operation		
Work lamps		
Steps/grab rails	. /	
Load chart condition	/	
Operators manual present	X	NOT PRESENT
Horn operation		1
Seat condition	/	
Fire extinguisher present	X	Nor Fitters
Set up level indicator		
Outriggers		
Vertical cylinder leaks	1	
Vertical cylinder hoses	/	
Horizontal cylinder leaks	1	
Horizontal cylinder hoses	1	*
Outrigger pad condition	1	
Horizontal slides	/	
Outrigger box cracks	1	VISUALCHECK
Outrigger pin and retainers		

Plant Report cont.

S/No:) 3099	Date:	10.09.2025

Other Comments:
CHANGED HYDRAULIC RETURN FILTER
LUBRICATE SLEW LING TEETH
CHECK BOOM EXTEND CABLES.
ADJUST TRACKS

Work carried out by: G. WITSHIRE	Signature: ## #################################
Company: ALAHA PLANT SERVICES	Date: 10.09.2025
	PLANOT MECHANOIC

N/A: Not applicable. N/S: Not serviced. X: Requires attention. *: Refer to comments

At the time of inspection this machine is in good working order, no obvious faults to the items inspected were found other than those out lined in this report.

This inspection does not include any non-destructive tests on structural items such as booms, outriggers etc unless otherwise stated.