# PHANT SERVICES

24 Brushwood Drive Rouse Hill NSW 2155

Plant Report			Tel: 0428 240 448
Location: BIACKTOWN NO Owner: PARRAMATTA CRAN MAEDA	ORVSHOP UES	Date: (2.09.) Unit No: Model: Mc 28	5S/No: P3251
Inspection: Service: Warranty:		Hours Upper: Hours Carrier: - Kilometres:	
Copy Of Certificates Crane Hoist Ropes Main Auxiliary Hooks Main Auxiliary	Attached Yes/No Yes/No Yes/No Yes/No Yes/No	Current Yes/No Yes/No Yes/No Yes/No Yes/No	
Description	OK	Re	emarks
Engine			,
Oil Leaks	1	CHANGES OIL	4 FILTARS
Water leaks			
Radiator/heater hose condition	4		
Vee belt condition and adjustmer			
Fan bearing condition Air induction system	MA		
Air riduction system Air cleaner restrict level		NEW ELEMEN	FEMA
Exhaust system/muffler		NEW ELEMEN	, Filley
Radiator core condition			
Engine Mounts			
Battery condition/leads			
Drain air tanks	NA		
Drive Train	1 (1-1)		
Transmission oil leaks		,	
Wheel hub/axle oil leaks	N		
Wheel nuts/locks	A		
Drive shaft/uni joints/drive tracks	1	HUB OIL CHA	NGED
Tyre condition: % / pressure PS	: /	Axle 1 LH	RH
		Axle 2 ""	433
		Axle 3 ""	<b>4.9</b>
	NA	Axle 4 ""	66.33
		Axle 5 ""	6 27
		Axle 6 ""	<b>66.33</b>
Axle pivot condition			
Axle pivot lock out			

## Plant Report cont.

S/No: P3251

Date: 12-09-2025

Description	OK	Remarks	
Steering/Braking System			
Steering cylinder oil leaks			
Tie rod condition			
Tie rod end condition	NA		
Service brake operation/adjustment	/-		
Park brake operation/adjustment			
Fluid level service/park			
Winches		Main	Auxiliary
Mounting bolts	/		
Oil leaks – gear box			
Oil leaks – hydraulic motor	1		
Brake linings/adjustment		MERNAL	
Brake oil/fluid leaks	5		NA
Drum cracks		VISUAL CHECK	
Safety pawl operation	NA		
Disorderly rope winding			
Oil level/gear box	/	OIL CHANGES	,
Ropes and Hooks			
Rotation of hook			
Deformation of hook			
Safety latch fitted	1		
Deformation of rope guard	1		
Rotation of sheaves			. /
Lubricate sheaves	NA	×	PA
Kinks in wire rope			
Broken strands in rope			
Corrosion of rope			
Wedge correctly fitted			
Rope clip fitted to end		1	
Slew System			
Slew table cracks	1	VISUAL CHECK	
Slew motor leaks	5		
Slew box leaks			
Slew box mounting bolts			
Slew box oil level	1	CHANGED OIL	
Slew brake operation			
Rotary connection leaks	/		*
Upper house lock pin	MA		

## Plant Report cont.

S/No: P3251

Date: 12.09.2025

Description	OK	Remarks
Boom		
Hoist cylinder leaks		
Hoist cylinder pins and retainers	1	GREASES
Hoist cylinder hose condition		
Boom pivot pin and retainers		GREASE)
Inspection of boom cracks/damage	1	VISUAL CHECK
Sliding wear pad condition		GREASED
Tele cylinder leaks	/	
Tele cylinder hoses		
Angle indicator condition	/	
Inspect fly damage	11/	
Fly retaining pins	A	
Fly storage correct	/	3
Boom sheaves		
Fly sheaves	NA	
Cab And General		
Operation of all gauges		
Control levers/play		
Load meter		
Warning buzzers		
Windscreen condition	N	·
Wiper condition	A	
Anti two block operation		
Work lamps		
Steps/grab rails	N/A	
Load chart condition		
Operators manual present	X	NOT PRESENT
Horn operation		
Seat condition	MA	,
Fire extinguisher present	X	NOT FITTED
Set up level indicator		
Outriggers		
Vertical cylinder leaks		
Vertical cylinder hoses		
Horizontal cylinder leaks	N	
Horizontal cylinder hoses	A	
Outrigger pad condition	/	
Horizontal slides	/	
Outrigger box cracks		VISUAL CHECK
Outrigger pin and retainers		

#### Plant Report cont.

S/No: 73251	Date: 12.09.2025

Other Comments:
CHANGES HYDRAULIC RETURN FILTER
ADJUSTED TRACKS
LUBRICATE SLEW RING TEETH
LUBRYCATE BOOM EXTEND CABLES
Work carried out by: G. WICTSHIPE Signature: Buttst.
1201 PILOT STOLINGTS - 1209 2025
Date: 1201. 2000  PART MECHANIC,

At the time of inspection this machine is in good working order, no obvious faults to the items inspected were found other than those out lined in this report.

This inspection does not include any non-destructive tests on structural items such as booms, outriggers etc unless otherwise stated.